

Statement of Evidence:

L141

North Quarter Corner of Section 14, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.

6" Bur Oak	S 17 E	317 links
5" Aspen	N 72 W	34 links

1961 M.W. Carley ties:

TP	N	39.25
12" Poplar	S	58.45
6" Poplar	SW	75.15

2002 No other survey records were found on this corner in the Benton County records.

2005 MN/DOT survey crew found iron pipe that fit occupation of east-west road and fence line north. Measured 2652.56 feet to the NE corner and 2660.45 feet to the NW corner.

County Coordinates obtained by GPS

NAD 83 (1996 Adjustment)

N- 121281.175

E- 502741.843

2005 Certificate of Survey by William Lunser, LS 9394, shows iron at the corner being 2660.48 feet east of the SW corner of Section 11.

2009 Westwood Professional Services, Inc. found a ½ inch iron pipe on the centerline of E/W road and fence line to the north.

The Minnesota Department of Transportation file a Certificate of Location of Government Corner (Document Number 368986).