

Statement of Evidence:

L181

The North Quarter Corner of Section 18, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this corner and set a wood post at the corner location with bearing trees marked:

12" Bur Oak	S 75 W	360 links
15" Bur Oak	N 62 E	152 links

1980 Paul Wollen, LS 10461, set an iron monument for the corner. Notes do not show how corner was determined or set.

2002 Westwood Professional Services, Inc. found a ½ " iron pipe 1-foot west of a fence line north. The pipe was found to be 24.3 feet north and 6.0 feet east of the lost position between section corners.

County Coordinates obtained by Side-tie

NAD 83 (1996 Adjustment)
N- 121341.044
E- 481478.738

2009 Westwood Professional Services, Inc. found a ½ " iron pipe 2,860.00 feet from the NW corner of Section 18 and 2,654.90 feet from the NE corner of Section 18. The ½ " iron pipe is in agreement with the position reported in 2002. Reference ties were established.

County Coordinates
NAD 83 (1996 Adjustment)
N- 121341.044
E- 481478.738