

Statement of Evidence:

G363

East Quarter Corner of Section 36, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1849 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

6" Blk Ash	S 67 E	5 links
6" Basswood	S 47 W	9 links

1930 County Engineer's notebook No. 60 for CR 25 running north-south indicates a nail set for the corner and with County Surveyor's Record Book 1, page 457, notes the following reference ties:

Cor FP	E	21.6
FP	SE	31.0

Notes show town road west and fence line east. Stationing gives distances of 2744.6 feet to the SE corner and 2698.0 feet to the NE corner.

1959 County Engineer's Notebook No. 208 contains a survey for CSAH No. 25 running south to north on the section lines. Corner is shown as a spike set in center of road with town road west. Ties:

Post SW	28.8	Post NW	27.55
---------	------	---------	-------

Stationing gives distances of 2745.7 feet to the SE corner and 2698.0 feet to the NE corner with a delta angle of 0-22' right.

2001 Westwood Professional Services, Inc. found an iron at the centerline of roads north/south and a tree line east/west.

2004 Measured 2741.69 feet to the SE corner and 2701.68 feet to the NE corner. Found pipe agrees reasonably with 1930's assumed corner and accepted pipe as marking the obliterated corner position.

County Coordinates Obtained by GPS to 1/2 " iron pipe:

NAD 83 (1996 Adjustment)

N- 134860.634

E- 510598.428

2010 The Benton County Surveyor's Office found the 1/2" iron pipe with unreadable cap, which was accepted in 2004 as marking the corner. A nail with Benton County Surveyor washer was placed over the found iron and the 2004 coordinates were verified.