

Statement of Evidence:

L261

North Quarter Corner of Section 26, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded.

8" Bur Oak	N 14 3/4 W	52 links
6" Bur Oak	S 8 1/4 E	61 links

1940's MN/DOT road alignment map (File No. 33-18) notes the corner at fence line north and west and 50.5 ft north of the centerline of TH 95.

1977 Paul Wollen, LS 10461, found a wood post at the intersection of a fence line north/south/east/west and replaced it with a 1/2" pipe. He filed a Certificate of Location (#147247).

1992 James Nielsen, LS 11865, found a 1/2" pipe and a fence line north/south/east/west. He filed a Certificate of Location (#216761).
County Coordinates obtained from MN/DOT
NAD 83 (1986 Adjustment)
N- 110641.427
E- 502869.554

2004 Danny Kron, LS 42621, searched corner area and found no evidence of the pipe as the area had been graded. He reset the corner from previous survey information and one tie from Nielson's Certificate. He measured 2647.35 feet to NW corner and 2672.72 feet to the NE corner.
County Coordinates obtained by traverse by Surveying & Engineering Professionals, Inc.
NAD 83 (1996 Adjustment)
N- 110642.803
E- 502869.149

2005 Note: MN/DOT plans to reset corner from 1992 coordinates, which is within a foot of the corner set by Kron. Mr. Kron has agreed.
County Coordinates from 1994 location
NAD 83 (1996 Adjustment)
N- 110641.641
E- 502869.361

2009 Westwood Professional Services, Inc. found a CIM and measured 2672.66 feet to the NE corner of Section 26 and 2647.69 feet to the NW corner of Section 26. CIM location agrees with 2005 coordinate position. Reference ties were established.