

Statement of Evidence:

G281

North Quarter Corner of Section 28, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Aspen

S 24 E

466 links

2002 No record evidence of this corner has been found in the Benton County records.

2006 The Benton County Surveyor's Office found an east-west fence line and a field fence line (not line fence) south. The east-west fence, when projected west, falls 28 feet south of the section corner and truncates at the west sixteenth (not built to the section corner). Believing the east-west fence to not be built on the section line and the fence south to be a fence of convenience, a ½-inch iron pipe capped RLS 19552 was set at the lost position.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-142819.723

E-492124.209