

Statement of Evidence:

G301

North Quarter Corner of Section 30, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing tree was recorded.

10" Blk Oak	S 34 W	405 links
-------------	--------	-----------

2001 Westwood Professional Services, Inc. found a $\frac{1}{2}$ " iron pipe in east-west road and in approximate line with tree line south. Measured 2788.46 feet to the NW corner of Section 30.
County Coordinates determined from traverse information:
NAD 83 (1996 Adjustment)
N- 142809.95
E- 481473.45

2002 No record evidence of this corner has been found in the Benton County records.

NOTE: Iron pipe position is suspect, since it is at the GLO distance, being 42.25 chains = 2788.5 feet, from the NW corner.

2006 The Benton County Surveyor's Office found a $\frac{1}{2}$ " open iron pipe in the east-west centerline of 75TH Street Northeast on a tree line south. The distance west fits the GLO distance west practically flat as noted above and the proportioned distance east within 6 feet. No other evidence of the corner position was found to contradict the found iron pipe. Believing the iron pipe to be the best available evidence since it is located at the lines of occupation; it is accepted as marking the obliterated corner position, GPS coordinates were obtained and reference ties were established.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-142809.657
E-481473.331