

Statement of Evidence:

G331

North Quarter Corner of Section 33, Township 37 North, Range 30 West, Mayhew Lake Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

7" Blk. Oak	S 14 1/2 E	43 links
6" Blk. Oak	N 51 1/2 E	76 links

1926 County Engineer's notebook No. 51 and road alignment maps note the following reference ties (also shown in the County Surveyor's Record Book 1, page 451).

Corner F.P.	N	28.3
F.P.	NW	41.0

Fence lines running north and south.

Plans note a distance of 2693.0 feet to the NE corner Sec 33 and a distance of 2693.2 feet (notes 2692.8 feet) to the NE corner Sec 32. A delta angle of 00-32 Left (moving east to west). Fence lines north and south.

Undated notes call for a post at the corner.

2002 Westwood Professional Services, Inc. found a PK near the centerline of CSAH No. 4 (running east and west) and a 1/2" open iron pipe 33 feet south of the PK prior to road reconstruction. The location of the PK has a delta angle of 00-25-37 Left going from east to west and has distances of 2656.23 feet to the NE corner Sec 32 and 2680.09 feet to the NE corner Sec 33. Comparison to 1926 stationing along the CSAH 4 project fits within 3 feet of the found PK. The lost position of the corner falls 11.99 feet east and 9.87 feet south of the found PK nail. The PK nail fits reasonably well with occupation lines north and south. It appears the PK Nail, with the iron pipe to the south, has been used as the corner and the position could be accepted as the obliterated position of the corner.

County Coordinates Obtained by GPS to PK Nail

NAD 83 (1996 Adjustment)

N-137513.063

E-492053.703

County Coordinates Obtained by GPS to 1/2 " iron pipe R/W

NAD 83 (1996 Adjustment)

N-137480.150

E-492053.435