

Statement of Evidence:

Northeast Corner of Section 12, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey established this corner and note a wood post was set with bearing trees marked:

4" Willow	N 73 W	39 links
6" Willow	S 68 1/2 W	59 links

A line tree was noted as an 18" Blk Oak North 16.76 chains.

1930 County Engineer's Notebook No. 60 for CR 25 running north-south indicates a spike set for the corner.

1959 County Engineer's Notebook No. 208 contains a survey for CSAH No. 25 running south to north on the section lines. Corner is shown as a spike set in center of road at fence line west. Ties.

Guard W	11.5
Guard E	11.5

At north edge of bridge

1995 Kevin Festler, LS, found a PK nail with washer at the intersection of the centerline of a road north/south and a fence line west. He removed the PK nail and found no other evidence below. He set a 1/2" pipe capped RLS #16097. He filed a Certificate of Location (#230318).

Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to an iron pipe:

N- 126781.038
E- 510617.791

2004 MN/DOT survey crew found iron pipe.
County Coordinates furnished by MN/DOT to IP
NAD 83 (1996 Adjustment)
N- 126781.188
E- 510617.211

2008 Westwood Professional Services, Inc. placed a Pk nail and county washer flush with bituminous surface over found/existing monument

NAD 83 (1996 Adjustment)
N- 126781.188
E- 510617.211