

Statement of Evidence:

L335

The South Quarter Corner of Section 33, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post was set at this location and bearing trees were recorded.
4" Blk. Oak S 73 1/2 W 335 links

1969 Dilbert Rieke, LS 5094, re-established the corner by proportionate measure between the NE and the NW corners of Section 4-35-30. He set a Sherburne County cast iron monument at the position. Corner appears to be 30 feet east and 10 feet south of the 4-way fence corner.

SEE SHERBURNE COUNTY STATEMENT OF EVIDENCE, CERTIFICATE, AND AFFIDAVIT – MN/DNR SET DIFFERENT CORNER.

1992 Minnesota DNR surveyor John Walker, LS 16098, did not accept the corner as set by Rieke in 1969 and set corner based on occupation lines. DNR corner is 35.28 feet SW of the Rieke corner. Corner position was accepted by Sherburne County Surveyor, Dan Nickols, LS 19839.

2002 Sherburne County Surveyor's Office notes all previous monuments and ties destroyed by road construction in 2000. Set 1" x 7' capped iron pipe.

County Coordinates converted from Sherburne County Coordinates
NAD83 (1986 Adjustment)
N – 100035.60 E – 492451.56

2003 County Coordinates Obtained by GPS to 1" capped iron pipe (DNR Corner)
NAD 83 (1996 Adjustment)
N- 100035.827
E- 492450.742

2009 Westwood Professional Services recovered the 1" capped iron pipe and updated reference ties. County Coordinates Obtained by GPS to 1" 2002 capped iron pipe (DNR Corner Position from 1992)