Certified, Filed and or Recorded on Dec. 16, 2008 AT 01:44PM

Signed: BW

MARILYN J NOVAK G V M

BENTON COUNTY MINNESOTA

MARILYN J NOVAK

COUNTY RECORDER

4TH	NORTHEAST Principal Meria corner location sho	Corner of Minnessown on the sketch: found aCAST	of Section _ sota, County of	<u>18</u> , Townshi	ip <u>37N</u> , Rai Benton		
		I left monument as found lowered monument removed monument (explain)					
	FIELD SEC 7	SET PK O	817		JEC. B TREES T SPIKE IN ' POPLAR	78 17	
	TREES SEC 18	FOUND PK 143.30 FOUND PK 143.30 IN CMP	1 1	邻	业 LOW WET SEC.17	**************************************	
Statement of evidence for this corner location is on back of this page.							
		document was resear Land Surveyor under				supervision	

Signature / County Surveyor License No. 45872

Benton County Surveyor's Office Jason W. Oberg, Deputy County Surveyor Minnesota License No. 45872

Statement of Evidence:

I182

Northeast Corner of Section 18, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

US General Land Office survey established this corner and set a wood post and bearing 1855 trees were recorded as follows:

10" Elm

S 31 W

75 links

6" Elm

N 2 ½ E

22 links

County Engineer's Notebook No. 80 for survey of SAR 6 running north to south. Notes 1927 show corner marked by an iron bar set in center of road and on fence line east and west. Notes give a delta angle of 0-36' right. Ties:

SE 29.0'

4th FP

SW 47.3

Later ties also listed in County Surveyor's Record Book 2, page 240, to a hub at corner on fence line east-west. Ties:

PP Cor FP SW

W

36.05

49.5

County Highway ties: 1937

> TP SE

39.4

4th FP SW 40.5

County Engineer's Notebook No. 163 contains a road survey for SAR 6 running from 1944 south to north on section line. Corner is shown marked by a 2" hub set in center of road with fence lines east and west. Ties:

PP

SW 49.5

Cor. FPW 36.0°

- County Engineer's Notebook No. 196 contains a road survey for SAR 6 running from 1953 south to north on section line. Same information as in 1944.
- William Lunser, LS 9394, found 1/4 " iron pin per County Highway plans which showed 1979 corner in north-south road and in line with fences east-west. He set ½ " iron pipe.
- William Lunser replaced iron pipe with cast iron monument and filed Certificate of 1988 Location (Doc. No. 191268).
- The County Surveyor's Office searched and found a cast iron monument, as placed by 2008 Lunser in 1988, along centerline of a north-south road (County Road No. 6). Running from north to south gives a deflection angle at the corner of 0°34'23" right, which agrees with the 1927 deflection angle of 0°37' right. Position falls in line with tree lines to the east and west. The position is accepted as the best evidence. Ties were updated.

County Coordinates obtained by GPS NAD 83 (1996 Adjustment) N-153807.372 E-547364.753

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER							
NortheastCorner of Section 18,Township 37,Range 28,4 th _ P.M.							
STATE OF MINNESOTA, County ofBenton							
At the corner location shown on the sketch:							
□ On found a							
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)							
On 12-8-88 placed a Benton County Cast Iron Monument							
DATE							
SKETCH OF REFERENCE TIES							
P.K. in PP 168.96 O							
PK. in PP. 143.61 O PK. in Culvert 226.81	Spike Top Cor. F.P. 51.69 Cor. 22.2992						
Statement of evidence relative to this corner location is on back of page.							
The state of the state of the state of the state of page.							
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of						
my direct supervision.	I hereby certify that this document was filed in						
Western 12/15/88 SIGNATURE DATE	the Reg. of Deeds office atM. on the day of A.D., 19						
Registration No. 9394	Register of Deeds						
☐ Land Surveyor, ☐ Professional Engineer	By,Deputy						
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.						

Statement of Evidence:

න න

 \sim

0

- 9-19-79 County Highway Road plans showed this corner to be at centerline of road north-south and a fence line east-west. Found 1/4" pin at this location and verified ties per County Road plans. Set 1/2" iron pipe at this location.
- 12-8-88 Found 1/2" iron pipe as set in 1979 and verified ties. Set Benton County Cast Iron Monument at this location.

BENTON COUNTY, MN
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON
JAN 12 12 09 PM 189
ALIGE C. ENGELMEYER
COUNTY RECORDER